



How to Shut Down National Optronics Edging Equipment **During Down Time**

7E/7Ex

- Empty and clean the water tank to stop corrosion of parts and possible mold growth
- Disconnect all water lines and blow out remaining water
- Clean edger completely
- During complete shutdown of edger, apply a light amount of 3:1 oil onto the size and bevel lead screw assemblies and perform a SIZE and BEVEL carriage movement by pressing the SIZE AND BEVEL buttons at the bottom of the BURN-IN screen using the GREEN F-KEY
- Unplug the edger from the power source

QM-X4

- Empty and clean the water tank to stop corrosion of parts and possible mold growth
- Disconnect all water lines and blow out remaining water
- Clean edger completely
- Unplug the edger from the power source

For National Optronics tech support questions, please contact
972.677.2777

